

**To:** Loesel, Matthew[loesel.matthew@epa.gov]  
**Cc:** Knabel, Jessica[Knabel.Jessica@epa.gov]  
**From:** Foster, Althea  
**Sent:** Thur 8/13/2015 12:03:40 PM  
**Subject:** FW: GKM - Pics  
20150811\_105416.jpg  
20150811\_110642.jpg  
20150811\_110704.jpg  
20150811\_111246.jpg

**From:** McCasland, Mark  
**Sent:** Thursday, August 13, 2015 12:04 AM  
**To:** Loesel, Matthew  
**Cc:** Atkins, Blake; Brown, Jamesr; Crossland, Ronnie; Foster, Althea; Garcia, David; Hayes, Mark; Ngo, Kim; Restivo, Angela; Rinehart, Jon; Smalley, Bryant; Webster, Susan  
**Subject:** GKM - Pics

Irrigation Ditch recon. Some of the issues are some gates do not close all the way because of debris, age, etc. Some leak around the edges. Cleanup/mitigation plans have been discussed and have been initiated.

Mark McCasland  
US EPA Region 6  
Drinking Water Section (6WQ-SD)  
1445 Ross Ave, Suite 1200  
Dallas, TX 75202-2733  
(214) 665-8088 (w)

mccasland.mark@epa.gov